Release Notes

Release Note:	**Memor™ 11 Android™ 13 Version 2.15.37**	**Distribution Date:**	September 22, 2026
Product Involved:	Memor™ 11		
Description:	**Memor™ 11 Android™ 13 Version 2.15.37 Firmware Release**		
Business Unit:	Mobile Computers		

Distribution Scope: ☐ **Internal** ☒ **External – specify:** **Public**

Memor™ 11 Android™ 13 version 2.15.37.20260831

1. COMPATIBILITY

- Memor™ 11 GMS all versions.

Memor™ 11 Android™ 13 firmware version downgrade to any Android™ 11 firmware versions is ALLOWED (*)(forcing factory reset).

Memor™ 11 Android™ 11 firmware version upgrade to any Android™ 13 firmware versions is ALLOWED.

(*)Downgrading the firmware version may be subject to planned obsolescence of hardware components.

To check the Android™ version, go to Settings>About phone and read the Android™ version.

NOTE: when updating from Android™ 11 to Android™ 13 via OTA package, it is highly recommended to disable the screen timeout.

2. ENHANCEMENTS

2.1. Security Enhancements

a. Updated Extended Android security patches level at June, 2026 [Android security bulletin link: https://source.android.com/security/bulletin/2026/2026-06-01].

2.2. Miscellaneous Enhancements

a. Updated DL Scanner service to 3.2.0.0-r3 version including:
    a. Introduced ITF-14 as GTIN format for scanner formatting
b. Updated SDK Add-on to 1.51.0 version.
c. Updated DL SetupWizardScanner to 1.44.1 version.
d. Updated Scan2Deploy to 2.9.0 version.
e. Updated DL Settings to 2.30.0 version.

3. CORRECTED DEFECTS

3.1. Wi-Fi Corrections

a. Fixed an issue that caused the Wi-Fi MAC address and country code to be lost during a firmware update to a version that introduced support for a new FEM component (v2.07.16 or later, all of which are now out of public distribution). (235803)
b. Reviewed Wi-Fi power table for FCC 802.11a. (236562)

3.2. Miscellaneous Corrections

a. Fixed an issue where the screen rotation setting applied using the Scan2Deploy script was lost after visiting the Home screen. (224491)

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

4. KNOWN LIMITATIONS

4.1. Miscellaneous

a. Upgrading from Android 11 to Android 13 via OTA package may take a long time if the device screen goes off. (192705) Workarounds:
    a. Disable screen timeout, *Settings* → *Display* → *Screen timeout* → *Never Timeout*.
    b. Keep the device charged by USB cable
    c. Keep the device charged by cradle

5. FILES

- memor11_gms-user-ota-2.15.37.20260831.zip [Memor™ 11 Android™ 13 GMS 2.15.37]
- ReleaseNotes_Memor 11-Android 13-v2.15.37.pdf [this document]

6. OTHER NOTES

Android Security:

- Android security patch level June 5, 2025
- Android extended security patch level June 5, 2026

Other Dependencies:

- Scan2Deploy Studio 2.3.1 or newer
- Datalogic Android SDK 1.51
- Espresso Extension 2.15.37

Upgrade methods:

- Scan2Deploy Studio: see the specific *Scan2Deploy* section available in the *Memor™ 11 user manual*.
- Memor™ 11: installing OTA locally via *System Update* option available in *System* settings.
- SDK intent
- ADB sideload

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

7. SUPPORT

Datalogic Download area:

Memor 11 - Android - Products - Datalogic Developer Portal

Datalogic Support & Service:

Support and Service - Datalogic

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

8. HISTORY

Memor™ 11 Android™ 13 version 2.14.29.20260113s [*no longer publicly available*]

ENHANCEMENTS

Security Enhancements

- Updated Extended Android security patches level at January, 2026 [Android security bulletins links: https://source.android.com/security/bulletin/2026/2026-01-01].

Miscellaneous Enhancements

- Improved noise suppression during the phone call in both handset and loudspeaker modes. (218350)

CORRECTED DEFECTS

None

Memor™ 11 Android™ 13 version 2.13.28.20251229

Firmware version only for M11 Turkey model not publicly released

Memor™ 11 Android™ 13 version 2.13.27.20251211 [*no longer publicly available*]

ENHANCEMENTS

Security Enhancements

- Updated Extended Android security patches level at December, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-12-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 3.1.1.0.r2 version including:
  a. Always On status maintained at reboot when pin or password are set as lock screen
  b. Added alignment of the scanner camera id to the one specified in the firmware
  c. Do not allow setting scan mode to always on with scanner disabled
- Updated DL Settings to 2.24.3 version.

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated DL Battery Manager to 2.15.2 version.

CORRECTED DEFECTS

None

Memor™ 11 Android™ 13 version 2.12.25.20251113s [*no longer publicly available*]

ENHANCEMENTS

Security Enhancements

- Updated Extended Android security patches level at November, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-11-01].

CORRECTED DEFECTS

None

Memor™ 11 Android™ 13 version 2.11.24.20251029s [*no longer publicly available*]

ENHANCEMENTS

Security Enhancements

- Updated Extended Android security patches level at October, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-10-01].

Miscellaneous Enhancements

- Introduced support to new camera, display and flash memory hardware. (213685)

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that, in certain specific application contexts, could cause wedge data not to be received after the first successful decoding. (214886)

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Memor™ 11 Android™ 13 version 2.10.21.20250925 [*no longer publicly available*]

ENHANCEMENTS

Security Enhancements

- Updated Extended Android security patches level at August, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-08-01].

Miscellaneous Enhancements

- Updated SDK Add-on to 1.45.1 version.
- Updated DL SetupWizardScanner to 1.40.2 version.
- Updated Scan2Deploy to 2.7.0 version.
- Updated DL Battery Manager to 2.15.1 version.

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that caused the previously scanned code to be returned when target mode was enabled and configured to scan release. (213630)
- Fixed an issue that prevented AEQR Code Enrollment when multiple QR codes were generated. (212281)

Memor™ 11 Android™ 13 version 2.09.18.20250807s

Firmware version not publicly released

Memor™ 11 Android™ 13 version 2.08.17.20250617s [*no longer publicly available*]

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at June, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-06-01].

Miscellaneous Enhancements

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated DL Scanner service to 2.2.0.45-r3 version including:
    a. Add crop of the barcode in intent wedge
    b. Ignore ScanToDeploy v3 barcode if device is not provisioned yet
- Updated SDK Add-on to 1.45.0 version.
- Updated DL Settings to 2.24.1 version.
- Updated DL SetupWizardScanner to 1.39.1 version.
- Updated Scan2Deploy to 2.6.1 version.
- Updated DL Battery Manager to 2.15.0 version.
- Updated DL SoftSpot to 3.2.1 version.
- Introduced Virtual RAM Swap Policy option. (209801)
- Renewed Datalogic settings for Battery Management options.

CORRECTED DEFECTS

Miscellaneous Corrections

- Keyboard button to switch to QuickBoard is now available. (199042, 203736)
- Fixed an issue that prevented NFC from remaining off after reboot when it had been previously disabled. (209594)
- Fixed an issue preventing applications to send data to a BT peripheral connected to the device in SPP mode. (207948)

Memor™ 11 Android™ 13 version 2.07.16.20250523s

Firmware version not publicly released

Memor™ 11 Android™ 13 version 2.06.14.20250408s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at April, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-04-01].

CORRECTED DEFECTS

Miscellaneous Corrections

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Fixed a problem in the Bluetooth discovery routine that in some cases could prevent Memor 11 from discovering Bluetooth devices. (205216)

Memor™ 11 Android™ 13 version 2.05.13.20250303s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at March, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-03-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 2.2.0.44-r8 version.
- Updated SDK Add-on to 1.43.4 version.
- Updated DL Settings to 2.23.3 version.
- Updated DL SetupWizardScanner to 1.38.0 version.
- Updated DL Battery Manager to 2.13.0 version.
- Updated Scan2Deploy to 2.5.1 version.

Memor™ 11 Android™ 13 version 2.04.12.20250125s

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at January, 2025 [Android security bulletins links: https://source.android.com/security/bulletin/2025-01-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 2.2.0.44-r4 version including:
    a. Snap OCR feature
- Updated SDK Add-on to 1.43.1 version.
- Updated DL Settings to 2.23.0 version.
- Updated Scan2Deploy to 2.5.0 version.
- Updated DL SoftSpot to 3.1.0 version.
- Introduced support to new FEM Wi-Fi amplifier hw component. (203034)

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Introduced and enabled by default Bluetooth silent paring feature for Datalogic trusted devices. (197120)

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that caused USB MTP settings not to be retained on device reboot. (200678)

Memor™ 11 Android™ 13 version 2.03.09.20241216

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at November, 2024 [Android security bulletins links: https://source.android.com/security/bulletin/2024-11-01].

Miscellaneous Enhancements

- New boot animation logo, wallpaper, and dashboard icons style. (185165, 196844)
- Updated SDK Add-on to 1.39.11 version.

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue causing in some cases BLE not receiving data. (198853)
- Fixed an issue so that, upgrading the system from A11 to A13, applications lose the ability to access their own External Storage. (197862)

Memor™ 11 Android™ 13 version 2.02.07.20241018

Firmware version not publicly released

Memor™ 11 Android™ 13 version 2.01.04.20240910s

ENHANCEMENTS

Security Enhancements

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

- Updated Android security patches level at September, 2024 [Android security bulletins links: https://source.android.com/security/bulletin/2024-09-01].

Miscellaneous Enhancements

- Updated DL Scanner service to 2.2.0.42-r2 version.
- Updated SDK Add-on to 1.39.9 version.
- Updated DL Settings to 2.19.10 version.
- Updated DL SetupWizardScanner to 1.36.0 version.
- Updated DL Battery Manager to 2.7.3 version.
- Updated Scan2Deploy to 2.3.1 version.
- Updated DL SoftSpot to 3.0.3 version.

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that if a wake-up source key was remapped to send an intent this was not sent when the device was in suspend mode. (191673)

Memor™ 11 Android™ 13 version 2.00.01.20240710

ENHANCEMENTS

Security Enhancements

- Updated Android security patches level at June, 2024 [Android security bulletins links: https://source.android.com/security/bulletin/2024-06-01].

Miscellaneous Enhancements

- OS Android updated to version 13.
- Introduced support to Bluetooth silent pairing feature.
- Introduced support to PTT button functionality.
- Introduced support to host name configuration.
- Improved key remapping feature extending mapping functionalities including:
    a. Input a character or text
    b. Send an intent
    c. Everytime press
    d. Everytime release

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

e. On long press
f. On very long press
g. On single press
h. On double press

- Updated DL Scanner service to 2.2.0.40-r5 version.
- Updated SDK Add-on to 1.37.6 version.
- Updated DL Settings to 2.19.3 version.
- Updated Scan2Deploy to 2.3.0 version.

CORRECTED DEFECTS

None

© 2007-2026 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U.. Falcon, the Falcon logo, the Joya logo, Memor, Magellan, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Rida, Marvis, Uniq, Impact, CODIScan are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Motionix, ScaleSentry, ScanSentry, QuadVision, Gryphon, Heron, illumix, Joya, Shopevolution, WebSentinel, SafeSwap, Datalogic Connect, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.