Release Notes

Release Note:	**Falcon™ X4 WEC7 Version 2.02.073.01 International**	**Distribution Date:**	March 24, 2021
Product Involved:	Falcon™ X4 Windows Embedded Compact 7.0		
Description:	**Falcon™ X4 Windows Embedded Compact 7.0 Version 2.02.073.01 International Firmware Release**		
Business Unit:	Mobile Computers		

Distribution Scope: ☐ **Internal** ☒ **External – specify:** **Public**

Falcon™ X4 Windows Embedded Compact 7.0 version 2.02.073.01 International

1. COMPATIBILITY

- For use on Falcon X4 Pilot or Production units.
- Recommend using DXU version 2.0.0.1543 or later. Older versions of DXU used with WEC7 firmware version 1.70 or later may crash when attempting to change Wi-Fi profiles. WEC7 DXU files created prior to firmware version 1.70 can still be applied to devices, but can no longer be modified in DXU version 2.0 or newer.
- Units equipped with 2D Auto Range plus scanner module cannot be downgraded to firmware 1.70 or previous versions.
- Units equipped with 1D scanner module must be cold booted if firmware is downgraded from 2.00 version or clean booted if firmware is upgraded to 2.01 version.
- Be sure that the mobile computer's battery is well charged to avoid any risk of unrecoverable issues during the upgrade. Datalogic recommends you USE A POWERED SINGLE SLOT DOCK or A USB POWER ADAPTER.
- Do NOT operate the mobile computer until the update is completely finished. Do NOT press keys on the keyboard. Do NOT touch the touchscreen. Do NOT press the ON/OFF button. Do NOT press the pistol trigger. Do NOT disconnect the mobile computer from external power during the update.

2. ENHANCEMENTS

None

3. CORRECTED DEFECTS

3.1. Decoding Corrections

a. Fixed an issue causing Standard 2 of 5 barcode with 2-bar start/stop to be not decoded. (136404)

4. KNOWN LIMITATIONS

4.1. Bar Code Decoding

a. The 2D scanner does not decode with picklist enabled when aiming at the composite or add-on portion of a label. (65389) Workaround: Aim at the base label.
b. Read rate of 2D scanner is very low on Iphone box labels. (79996)
c. The 1D scanner may not decode EAN barcode with low quiet zone. (87480)
d. Group Separator may not be reported scanning Code-128 label. (133718)

4.2. Wi-Fi

a. Under some circumstances Wi-Fi could not connect using PEAP-MSCHAP V2 security protocol with Radius authentication server. (76537, 76539)
b. Wi-Fi auto profile feature is slow in switching between radio profiles. (87783)
c. Device working with Aruba network equipment might temporary lose radio connection during roaming. (97258) Workaround: configure fixed channels on AP side.
d. Device working with legacy Motorola network equipment might unexpectedly lose radio connection during roaming. (97262) Workaround: disable/enable wi-fi module or reboot device.
e. In some cases device might lose radio connection temporary during roaming phase. (103419, 106339, 107392, 107475, 114237, 121935, 132773, 134201, 135121, 136007)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

4.3. DXU and DDU

Refer to DXU internal release note for further information about corrected defects and known limitations.

4.4. SDK

Refer to SDK internal release note for further information about corrected defects and known limitations.

4.5. Miscellaneous

a. Disable automatic SIP option is not supported in MS IE. (72150)
b. In some very rare case vertical stripes could be displayed on screen at resume. (136376) Workaround: reboot device.

5. FILES

- nk.img [Falcon™ X4 Windows Embedded Compact 7 version 2.02.073.01 International]
- ReleaseNotes_Falcon X4_WEC7_v2.02.pdf (this document)

6. OTHER NOTES

Other Dependencies:

- Datalogic DXU v2.0.0 or newer
- Datalogic SDK v2.2.0.67 or newer

Upgrade Methods:

- Datalogic DXU: see the specific DXU section available in the device user manual.

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

7. SUPPORT

Datalogic Download area:

https://developer.datalogic.com/mobile-computers/products/falcon-x4/windows/firmware

Datalogic Technical Support Request:

https://www.datalogic.com/eng/support-service-sp-18.html#technical_support

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

8. HISTORY

Falcon™ X4 Windows Embedded Compact 7.0 version 2.01.073.02 International

ENHANCEMENTS

No enhancements are implemented in this release.

CORRECTED DEFECTS

Decoding Corrections

- Fixed an issue on 1D scanner causing GS1-128 labels to be not decoded when Code 128 was disabled. (123111)
- Fixed an issue for 2D scanner causing device battery consumption when placed in suspend prior to pulling the trigger. (132670)

Falcon™ X4 Windows Embedded Compact 7.0 version 2.00.073.03 International

ENHANCEMENTS

Decoding Enhancements

- Updated 1D scanner to 2.0.0.2 version. (112410)
- Updated 2D Auto Range scanner to 2.2.0.6 version. (114289)

Wi-Fi Enhancements

- Updated radio adapter driver to MCP-8.0.0.47_Release_3.11 version improving connection logic to non-Enterprise grade Wi-Fi systems without controller.

CORRECTED DEFECTS

Wi-Fi Corrections

- Fixed an issue causing in some cases to lose radio connection temporary during roaming phase. (111882, 115092)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

Falcon™ X4 Windows Embedded Compact 7.0 version 1.90.073.02 International

ENHANCEMENTS

Miscellaneous Enhancements

- Updated WEC7 embedded certificates list. (105709)
- Added the ability to download an exe file in Deployment section for Scan2Deploy. (106168)

CORRECTED DEFECTS

DXU and DDU Corrections

- Corrected an issue that prevented DXU to setup hidden Wi-Fi profile. (108523)

Miscellaneous Corrections

- Fixed an issue that caused full screen application to be not properly displayed when display auto-rotation feature was enabled together with taskbar disabled.

Falcon™ X4 Windows Embedded Compact 7.0 version 1.80.073.06 International

ENHANCEMENTS

Bar Code Decoding Enhancements

- Improved performance for 2D Auto Range scan engine. (103524)

Miscellaneous Enhancements

- Upgraded Windows Embedded Compact 7 to Update 73 September 2019. (98201)

CORRECTED DEFECTS

DXU and DDU Corrections

- Corrected taskbar display issue in DDU with full screen application after display rotation. (103209)
- Corrected an issue preventing to apply wi-fi channels setting using DXU. (103897)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

- Corrected an issue preventing to get DXU configuration if pre-v2.0 DXU configuration was applied before. (103899)
- Corrected an issue that prevented DXU to setup wi-fi profile with WEP encryption. (105597)

Miscellaneous Corrections

- Fixed an issue that caused characters drop when quickly typed. (104496)
- Fixed an issue that prevented to disable all 5 GHz channels in the wi-fi applet. (104742)

Falcon™ X4 Windows Embedded Compact 7.0 version 1.70.071.05 International

ENHANCEMENTS

Bar Code Decoding Enhancements

- Included support to DotCode for both 2D Auto Range and Halogen2-DL scan engines. (74693)

Wi-Fi Enhancements

- Updated radio adapter driver to MCP-8.0.0.47_Release_3.10 version improving the roaming logic for the single AP use case. (98368)

Miscellaneous Enhancements

- Upgraded Windows Embedded Compact 7 to Update 71 March 2019. (98201)

CORRECTED DEFECTS

No corrections are implemented in this release.

Falcon™ X4 Windows Embedded Compact 7.0 version 1.61.068.02 International

ENHANCEMENTS

Wi-Fi Enhancements

- Now Control Panel>System>Device Name is also adopted as Cisco radio client name. (97256)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

CORRECTED DEFECTS

Miscellaneous Corrections

- Fixed an issue that caused DXU Remote Control to stop working when device was connected using USBLan protocol. (96813)

Falcon™ X4 Windows Embedded Compact 7.0 version 1.60.068.05 International

ENHANCEMENTS

Bar Code Decoding Enhancements

- Updated 2D Auto Range scanner to 1.0.2.1 version to improve DataMatrix reading at longer distances. (90421)

Wi-Fi Enhancements

- Improved EAP configuration user interface in DL Wi-Fi applet. (93780)
- DL Wi-Fi applet has been changed to persist the registry when 'Apply' button is pressed. (85486)

Miscellaneous Enhancements

- Introduced support for PFX certificates to the Certificates control panel. (90822)

CORRECTED DEFECTS

Bar Code Decoding Corrections

- Composite "Convert to GS1-128" option works if the Composite label embeds valid GS1-128 Application Identifiers in it. (63747)
- When "Required 2D component" is enabled, the 2D scanner reports GS1 DataBar Expanded labels with their composite components only if 1D label does include a linkage flag indicating to the reader that it should look for a 2D part. (65401)
- Fixed an issue that caused the 1D scanner to read inverse 1D code only if maximum settings were enabled. (94205)

Wi-Fi Corrections

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

- Fixed an issue causing Wi-Fi missing connection using EAP-TLS security protocol with certificate. (79463)
- Device can obtain DHCP address from BINTEC router setting the following specific system registry entry for DHCP: [HKLM\Comm\tiwlnapi1\Parms\TcpIp]"DhcpConstantRate"=0. (88371)
- Now device can connect to 5GHz Wi-Fi not broadcasted radio profile after rebooting. (89922)

Miscellaneous Corrections

- Fixed an issue that might cause device to lock up if inserted into an Ethernet dock while suspending. (92141)

Falcon™ X4 Windows Embedded Compact 7.0 version 1.50.068.03 International

ENHANCEMENTS

Decoding Enhancements

- Introduced support to new 2D Auto Range scanner module.

Wi-Fi Enhancements

- Introduced support to EAP-TLS protocol 1.2 version.

Miscellaneous Enhancements

- Updated EVL WEC7 library to 1.2.3.0 version.

CORRECTED DEFECTS

Bar Code Decoding Corrections

- Fixed an issue in the 2D scanner that allowed Composite labels longer than the maximum length value to be decoded. (63700)
- Fixed AIM ID of Japanese Postal code for 2D scanner. (70135)
- Now minimum decoding length setting for Code 128 is maintained. (81376)

DXU and DDU Corrections

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

- Now each registry entry in DXU has a unique key path - value name. (83466)
- Default extension settings have now been added to DXU for both 1D and 2D scanners. And conditional add-ons are only displayed in DXU for 1D scanners. (83500)
- Corrected order of 2D symbologies in DXU and fixed incorrect symbology names. (83501)
- Postal symbologies added to DXU for 2D scanners. (83502)

Miscellaneous Corrections

- Fixed an issue causing longer time to delete files stored in flash memory on newer devices. (85047)
- Fixed an issue that might rarely cause device to lock-up during use with different screen patterns. (69478, 70627)

Falcon™ X4 Windows Embedded Compact 7.0 version 1.42.068.01 International

Released for selected customers only

Falcon™ X4 Windows Embedded Compact 7.0 version 1.41.068.02 International

ENHANCEMENTS

No enhancements are implemented in this release.

CORRECTED DEFECTS

Bar Code Decoding Corrections

- Now in Release Scan target mode, after illumination turns on with no barcode, pressing scan button again the laser is turned on even if no label is decoded. (69553)

SDK Corrections

- Now EAP profiles can use Windows Credentials for network authentication. (82454)

Falcon™ X4 Windows Embedded Compact 7.0 version 1.40.068.03 International

ENHANCEMENTS

DXU Enhancements

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

- Now DXU does allow settings of advanced wi-fi options. (75370)
- PC connection settings are now available in DXU. (78905)

Miscellaneous Enhancements

- Introduced DL-Stager Scan2Deploy feature. (73957)
- Integrated support for new NEON scan engine. (77908)
- Updated EVL WEC7 library to 1.1.31.0 version. (78744)
- Updated radio adapter driver to MCP-8.0.0.47_Release_3.6 version implementing auto-recovery mechanism for radio module. (77716, 78743)
- Upgraded Windows Embedded Compact 7 to Update 68 June 2018. (79988)

CORRECTED DEFECTS

Bar Code Decoding Corrections

- Now the 2D scanner is able to decode closely spaced Code 128 labels on part number stickers. (67552)

Communications Corrections

- Now Bluetooth serial connections do not fail when rapidly suspending and resuming device. (73799)

Wi-Fi Corrections

- Now 802.11a channel is properly displayed in Stats tab of DL Wi-Fi applet. (77796)
- Fixed an issue that turning on "Driver Logging" option in DL Wi-Fi applet could produce false error message. (77911)
- Fixed an issue that caused EU model might not work properly on channels 149, 153, 157, 161. (78704)
- Now CCX setting is properly reported in DL Wi-Fi applet. (81941)

SDK Corrections

- Now DL Wi-Fi applet does correctly display 5 GHz channel list if unavailable channels have been selected with SDK function. (78299, 80859)
- Fixed an issue that caused the impossibility to run Java / Cre-Me JVM applications. (78418)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

Falcon™ X4 Windows Embedded Compact 7.0 version 1.31.067.01 International

Released for selected customers only

Falcon™ X4 Windows Embedded Compact 7.0 version 1.30.067.02 International

ENHANCEMENTS

Bar Code Decoding Enhancements

- Implemented 1D scanner aimer feature as blinking green line. (73604)

Wi-Fi Enhancements

- Introduced improved DL Wi-Fi applet for a better user experience as default alternative for WCU applet. (64134)

Miscellaneous Enhancements

- Updated radio adapter firmware to 4.2.3-Rev 8.9.0.0.45 version. (77714)
- Upgraded Windows Embedded Compact 7 to Update 67 Wave 5 March 2018 supporting Transport Layer Security protocol (TLS) versions 1.1 and 1.2. (74994)

CORRECTED DEFECTS

Communications Corrections

- Fixed an issue that did prevent Bluetooth Hands-Free profiles to automatically reconnect after a reboot. (59407)

SDK Corrections

- Now SDK .NET allows to create WEP wi-fi profile. (76252)
- Now SDK .NET allows to create WPA-TKIP wi-fi profile. (76258)

Miscellaneous Corrections

- Now languages and/or code pages are properly supported in WEC7 for application developed for CE6. (75256)
- Cab file installation from FlashDisk\Cab folder is now silent. (76600)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

ENHANCEMENTS

Miscellaneous Enhancements

- Updated 1D scanner to 1.5.1.0 version.
- Updated EVL WEC7 library to 1.1.25.0 version.

CORRECTED DEFECTS

Bar Code Decoding Corrections

- Now the 2D scanner reports both pair of labels when "Require ISBT 128 Concatenation" is enabled. (48553)
- Fixed an issue to prevent the 1D scanner to incorrectly decode programming labels. (50223)
- Fixed an issue that could cause the 1D scanner to decode only a portion of a wide Standard 2 of 5 label. (63856)

Communication Corrections

- Fixed an issue that might cause the device to not connect to Ethernet if put in the Ethernet dock while resuming. (74050)

USB Corrections

- Fixed an issue to prevent device to not connect to a PC over Activesync/WMDC resuming from single slot dock. (74045)

Wi-Fi Corrections

- Now Wi-Fi channels setting is maintained at reboot also for ETSI models. (73172)

Miscellaneous Corrections

- Now RDP password setting is maintained after warm boot. (70832)
- Maximum size of the system RAM memory for WEC 7 is 128MB due to MS design. (64299)

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal

- Now Control Panel Owner Network ID settings are properly maintained at reboot. (74256)

Falcon™ X4 Windows Embedded Compact 7.0 version 1.20.065.05 English

First production release

© 2007-2021 Datalogic S.p.A. and/or its affiliates. All rights reserved. Without limiting the rights under copyright, no part of this documentation may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means, or for any purpose, without the express written permission of Datalogic S.p.A. and/or its affiliates.
Product specifications are subject to change without notice. Datalogic Proprietary & Confidential Information.
Datalogic and the Datalogic logo are registered trademarks of Datalogic S.p.A. in many countries, including the U.S. and the E.U. Falcon, the Falcon logo, the Joya logo, Memor, Elf, Lynx, Magellan, Jade, LaneHawk, PowerScan, QuickScan, Halogen, SoftSpot, Cobalto, Rida, DL-Axist, Marvis, Uniq, Impact are trademarks of Datalogic S.p.A. and/or its affiliates, registered in many countries, including the U.S.A and the E.U. All-Weighs, First Strike, Miotionix, ScaleSentry, Gryphon, Heron, Herbo, illumix, Joya, Shopevolution, WebSentinel, SafeSwap R-Series, Rhino, Blackline, Skorpio, 3GL, Datalogic Aladdin, Datalogic STAR Cordless System, Touch, PreScan, Scanalyzer, Sextante GZPS, SurroundScan, Cashier Training, Produce Rail, and Productivity Index Reporting are trademarks of Datalogic S.p.A. and/or its affiliates. The Bluetooth word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Datalogic Group companies is under license.
Android is a trademark of Google LLC.
All other trademarks and brands are property of their respective owners.

Datalogic Confidential Internal